

Home Energy Assessments Insulation Services Heating & Cooling

Certificate of Completion

Contact Name	3
--------------	---

Richard Robbins

Crew Member Names on Job

Account Name

118 Mattapoisett Neck Rd Mattapoisett 02739

Site ID

800852

Product Description	Line Item Description	Quantity	Installed Quantity
Floor- Remove and relocate floo	Floor- Remove and relocate floo	32.00	32
2" Polyiso on Kneewall	2" Polyiso on Kneewall	46.00	46
6" Open Blow Attic	6" Open Blow Attic	990.00	990
7" Open Blow Attic	7" Open Blow Attic	421.00	421
Air Sealing Hours	Air Sealing Hours	12.00	12
Attic Hatch- Insulate and Weatherstrip	Attic Hatch- Insulate and Weatherstrip	1.00	1
Attic Stair Cover with Carpentry (with a/s hours)	Attic Stair Cover with Carpentry (with a/s hours)	1.00	
Damming	Damming	154.00	154
Duct Sealing- 8hrs- insulated and less than 200ft	Duct Sealing- 8hrs- insulated and less than 200ft	1.00	01
Insulate Attic/Basement Door	Insulate Attic/Basement Door	1.00	
Propavents with baffle at base	Propavents with baffle at base	70.00	70
R19 6" Fiberglass Rim Joist	R19 6" Fiberglass Rim Joist	69,00	69
Vent Bath Fan to Flapper (wall/gable/soffit) Change B & hose	Vent Bath Fan to Flapper (wall/gable/soffit)	1.00	0

BAS: 2811	Pre Blower Door	Results: 498 C	Pos	st Blower Door Results: 3834	!
Reason for no Blower Door:	Kairh	5 · S	ru Flow:	Post Tru Flow:	
Additional Remarks/Comment	e: Bt	ylleady	Vente	d	
Date: 2/20/23	A	Da Da	te: 2/20/	23 Must	